

Oil Field Environmental Incident Summary

Incident: 20150713145924 **Date/Time of Notice:** 07/13/2015 14:59

Responsible Party: ENERPLUS RESOURCES USA CORPORATION

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: AGAVE 149-93 06C-4H TF

Field Name: MANDAREE

Well File #: 20103

Date Incident: 7/13/2015 **Time Incident:** 03:00

Facility ID Number:

County: DUNN

Twp: 149

Rng: 93

Sec: 6

Qtr: SW SE

Location Description: Prairie

Submitted By: Tony Lucero

Received By:

Contact Person: Josh Ruffo
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine	5	Barrels	5	Barrels		
-------	---	---------	---	---------	--	--

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

The entire quantity of released fluid remained contained on the well pad.

Potential Environmental Impacts:

None. The entire quantity of released fluid remained contained on the well pad.

Action Taken or Planned:

The well was shut in and the stuffing box seal were replaced. The contaminated material on the well pad was excavated and sent offsite for disposal at an approved facility.

Wastes Disposal Location: At an approved offsite disposal facility.

Agencies Involved: BLM, BIA and the Three Affiliated Tribes

Updates

Date: 7/13/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, remained on location according to the report. NDIC retains oversight.